Komatsu, 931XC - Harvester Komatsu - Inspection report

Images



Information

Brand: **Komatsu** Model: **931XC** Hours when delivery: **10840** Location: **Bullaren**

Base machine

Front axle: **Boogie** Automatic sprinkler: **Yes** Central lubrication: **Yes** Hood protection: **OK**

Tyres

Left-front-front: 30% Left-front-back: 30% Left-back-front: 30% Left-back-back: 30% Brand front: Nokian Front dimensions: 710/45x26,5

Diesel engine

Cooling system: Fair Adblue: Working

Hydraulics

Hydraulic system: Fair Other options: Vacuum pump & hydraulic filling pump

Cabin

Seat type: **3000 BeGe** Crane lever: **Fair** Control system: **MaxiXplorer** Windshield: **Fair** Platform: **OK** Service ladder: **OK** User manual: **Yes**

Crane

Crane: Fair Length (m): 10 Crane lights: Yes Serial number: 9313021241 Country: Sweden Model year: 2017

Year of manufacture: 2017

Rear axle: **Boogie** Ladder: **Fair** Gear box: **Fair**

Right-front-front: **30%** Right-front-back: **30%** Right-back-front: **30%** Right-back-back: **30%** Brand back: **Nokian** Back dimensions: **710/45x26,5**

Heatingloop in hydraulic tank: Yes Diesel heater: Fair

Hydraulic oil: Komatsu HE GEN II Natura

Seat condition: Fair Crane lever: EmE Work lights: LED Sun curtains: Fair Radio: Smart radio Data caliper: 500 mm Parts book: Yes

Model: 230H Boom system: Fair Make: **Komatsu** Year: **2017** Oil leakage: **OK** Knives: **Fair** Colour marking: **Yes** Aut. chain tensioner: **Yes** Model: **C144** Condition: **Fair** Multi tree handling: **No** Condition: **Normal** Stump treatment: **No**

Extra equipment

Type: **Koppom** Type: **Koppom** Condition: **30%** Condition: **30%**



Overall evaluation condition

Overall evaluation condition: Good