



Machine Evaluation Standard

| A EXCELLENT CONDITION | | Utility | Construction | Mining |
|------------------------------------|--|--------------------|-----------------|-----------------|
| AGE | | Less 2 years | Less 4 years | Less 4 years |
| FRAME/MAJOR STRUCTURAL COMPONENTS | | Less 2.000 hrs. | Less 4.000 hrs. | Less 4.000 hrs. |
| UNDERCARRIAGE OR TIRES | Minimum 50% life remaining on all components. Pins and bushings not turned. | | | |
| GENERAL APPEARANCE | Excellent. Close to "like new" condition. | | | |
| PERFORMANCE | Operationally sound. Meets all performance specifications. | | | |
| B VERY GOOD CONDITION | | Utility | Construction | Mining |
| AGE | | Less 3 years | Less 6 years | Less 6 years |
| FRAME/MAJOR STRUCTURAL COMPONENTS. | | Less 3.500 hrs. | Less 6.000 hrs. | Less 7.000 hrs. |
| | Structurally sound. | | | |
| UNDERCARRIAGE OR TIRES | Minimum 50% life remaining on all components. Pins and bushings not turned. | | | |
| GENERAL APPEARANCE | Very Good. Sheet metal & paint is good. Operators compartment is very clean. | | | |
| PERFORMANCE | Operationally sound. Meets all performance specifications. | | | |
| C GOOD CONDITION | | All Product Groups | | |
| AGE | No limit | | | |
| FRAME/MAJOR STRUCTURAL COMPONENTS. | No hour limitation. No significant Structural problems. | | | |
| UNDERCARRIAGE OR TIRES | Minimum 35% life remaining on all components. | | | |
| GENERAL APPEARANCE | Only minor leaks of any sort. No noticeable problems. May need paint. Sheet metal acceptable "as is." Operator compartment is acceptable. Hinge and pin bores show normal wear. | | | |
| PERFORMANCE | Operates and is job-ready. May need minor adjustments and repairs for peak performance. | | | |
| D FAIR CONDITION | | All Product Groups | | |
| AGE | No limit | | | |
| FRAME/MAJOR STRUCTURAL COMPONENTS. | May have visible cracks or repairable structural problems; high hours may limit/prohibit machine rebuild. | | | |
| COMPONENTS HOURS | High hours but operable. | | | |
| UNDERCARRIAGE OR TIRES | May need undercarriage or tires. | | | |
| GENERAL APPEARANCE | May need paint. Repairable sheet metal damage. Some leaks. Hinge and pin bores may need repair. | | | |
| PERFORMANCE | Operational but may need significant repairs to be job-ready. | | | |
| E POOR CONDITIONS | | All Product Groups | | |
| OVERALL CONDITION | Machine may start but is not fully operational. | | | |
| GENERAL APPEARANCE | General appearance would suggest machine is unusable and therefore not worth repairing to condition "Code D" status. | | | |
| DESTINATION | Machine destined to be demolished. | | | |